

Incident Report - (Incident UID - IMF/TTK/COI/TIT/25/00062)

Incident Information

Incident UID	IMF/TTK/COI/TIT/25/00062	Category Name	Fire and others
Incident Description	A small fire broke out near the electrical control panel due to a short circuit caused by water seepage during heavy rain. The fire was quickly extinguished by the in-house emergency response team using a CO2 extinguisher.	Status	FinalReportReleased
Site Name	Coimbatore	Department Name	Maintenance
Incident Date & Time	26-Sep-2025 01:10:00 AM	Created On	07-Oct-2025 11:32:07 AM
Reported By	Lalit Aditya Kola		


Sections

Category of incident	<div><div><input checked="" type="radio"/> Fire</div><div><input type="radio"/> Flood</div><div><input type="radio"/> Cyclone</div><div><input type="radio"/> Heavy rain</div><div><input type="radio"/> Epidemic disease</div><div><input type="radio"/> Local threat</div></div>
----------------------	--

Photograph of the incident

Attach: 1

Attachments



Immediate corrective steps taken

Immediate corrective steps taken

S.No.	Actions	Responsibility	Status	Completion date
1	Power isolated and area secured	Maintenance Supervisor	Completed	2025-09-26
2	Electrical inspection conducted and wiring replaced	Electrical Engineer	Completed	2025-09-27
3	Preventive maintenance checklist updated	EHS Officer	Completed	2025-09-28