



Doc No: MHCPL-EHS-PTW-07

location is known to All Shock Treatment chart is available and is understood through TBT.: **No**

Permit To Work Report - Hot Work (Permit UID - APA/NEW/QWERTY/HW/0002)

Permit Information

Permit Information					
Type of permit	Name of project/site	Contractor company	Name of client/contractor		
Hot Work	New Siteeeeeee	Aparna Constructions	Raj Kumar Pativada		
	Work Int	formation			
Start date / Close Date	2/27/2025 12:00:00 AM / 2/27/2025 12:00:00 AM	Work location			
Start time / End time	2/27/2025 6:11:00 AM / 2/27/2025 6:00:00 PM	Reference permit no.			
No. of workers	0	Tools/ equipment to be used			
Scope of work					
Description of work					
	Sec	tions			
	Haz	ards			
Electrical Shock	Carbon Fumes	Arc Flash	Burns 🗆		
Fire /Explosion	Person Fall	Equipment Fall	Other Hazards:		
	Precaution	ons Taken			
Isolation	LOTO Applied	Isolation Switch Available	Cordoned Area		
HIRA Undertaken □	Signage's Provided ☐	SOP	Grounding Provided □		
ELCB / RCCB Provided □	Awareness on expected emergencies ?	Other Precautions::			
	Toolbo	ox Talks	•		
Topics discussed:		Attach photo: 0			
	Job Spe	cific PPEs			
Safety Helmet □	Safety Shoes	Full Body Harness	Cover All		
Welding Face Shield ☐	Leather Hand Gloves □	Leather Apron □	UV Protection Shield □		
Other PPE's:		•			
	<u>.</u> Safety Con	siderations			
Has the area at the work location been cleared of all the combustible materials & any other lubricants etc?: No	Has a flashback arrestor at both sides (cylinder & torch) been provided to the gas-cutting set?: No	Have Suitable Fire Extinguishers/sand buckets been kept handy at the work site?: No	Have Welding Screen (Yellow) / wet gunny bag/fire blanket been used to protect against sparks?: No		
Vertical clearance. (at least 2 meters above the platform) (Supervision should be provided if sufficient clearance is not available): No	Is barricading being provided below while doing work at height?: No	Is the gas-cutting cylinder checked for any leakages?: No	Are the gas cylinders secured in a trolley using chains?: No		
Do all workers involved in hot work have proper training on safety procedures and equipment use?: No	Do welding machines have ELCB/RCCB and proper earthing?: No	Availability and use of PPEs. (Mandatory PPE + Leather Apron, Welding Face Shield, Leather Hand Gloves): No	Use of Full body harness with double lanyard & lifeline or anchor point.(while doing hot work at height): No		
Any other requirement (If Yes, please specify): Emergency exits are available, and Emergency vehicle and First-aid providers shall be assured during the work The Main Isolation Switch location is known to All Shock					

Approval and authorization

Requestor_Trial-1	Issuer_Trial-2	Approver_Trial-3	Reviewer_Trial-4
Name: Raj Kumar Pativada Phone: +919160948627 Requested On: 26-Feb-2025 06:12:01 PM	Name: Vaibahv Varun Issuer Phone: +911233123312 Issued On: 26-Feb-2025 06:12:42 PM	Name: Vaibhav Varun approver Phone: +911233123123 Approved On: 26-Feb-2025 06:13:20 PM	Name: NA Phone: NA Reviewed On: NA

Permit To Work Closure

Check 1 □	Check 6 □	Check 2: NA	Check 4: No
Check 7: 0			
Check 3:	Check 5:		

Permit To Work History

Created On	Created By	Comment	Attachments
27-Feb-2025 06:24:01 PM	Raj Kumar Pativada	The status has changed to Validation Issued -17. Assigned Issuer_Trial-2: Samar Kumar	
27-Feb-2025 06:23:25 PM	Raj Kumar Pativada	The status has changed to Validation Issued -17. Assigned Approver_Trial-3: Vaibhav Varun approver	
27-Feb-2025 01:04:37 PM	Raj Kumar Pativada	The status has changed to Pending Closure -19.	
26-Feb-2025 06:13:20 PM	Vaibhav Varun approver	The status has changed to Approved -1. Assigned Reviewer: Vaibhav Varun Reviewer	
26-Feb-2025 06:12:42 PM	Vaibahv Varun Issuer	The status has changed to Issued -2. Assigned Approver: Vaibhav Varun approver	
26-Feb-2025 06:12:01 PM	Raj Kumar Pativada	The status has changed to Requested -3. Assigned Issuer: Vaibahv Varun Issuer	