Doc No: MHC-EHS-PTW-08



Permit To Work Report - Blasting Work (Permit UID - MHC/VIP/BSR/BL/0010)

Permit Information

Type of permit	Name of project/site	Contractor company	Name of client/contractor
Blasting Work	Vipina	BSR Infra Ventures Private Ltd	Lalit Requester

Work Information


Start date / Close Date	2/11/2025 12:00:00 AM / 2/12/2025 12:00:00 AM	Work location	
Start time / End time	2/11/2025 3:22:00 PM / 2/11/2025 11:00:00 PM	Reference permit no.	
No. of workers	NA	Tools/ equipment to be used	
Scope of work			
Description of work			

Sections

Hazards

Fly Rock ▼	Dust 🗸	Fumes 🔽	Toxic Gases ☑
Miss-Fires ☑	Explosion 🗸	Fire 🔽	Vibration ✓
Noise ✓			

Attachments



Precautions Taken

Licensed Blaster 🗸	Blasting NOC ▼	Blasting Siren 🗸	HIRA Undertaken ☑
Signage's Provided ✓	Blasting SOP ▼	Controlled Blasting	Separate Containers for Explosive & ED's ☑
Awareness on expected emergencies ?			

Attachments



Toolbox Talks

Topics discussed: Attach photo: 1

Attachments



Job Specific PPEs

Safety Helmet ✓	Safety Shoes 🗸	Ear Plugs / Muffs 🔽	Reflective Vest 🔽
Hand Gloves ▼	Nose Mask ▼	Goggles ▼	

Attachments



Safety Considerations

The blaster must possess a valid license.: No	Explosive to be transported in road, in an Explosive van.: No	Explosive should not be carried in the same vehicle with detonators.: No	Vehicle should be equipped with a non-sparking metal or wooden floor.: No
Do not use damaged/deteriorated explosives and accessories.: No	No holes should be loaded except those that are to be fired in the next round of blasting. Holes loaded during one shift should be fired on the same shift.: No	Post guards with red flags at a safe distance around the site to prevent persons approaching the danger area inadvertently while the shots are being fired.: No	Ensure to handle miss-fires by authorised blaster.: No
Carryout blasting is in day light hours only.: No	All Blasting's should be controlled/muffed blasting's.: No		

Approval and authorization

Requestor	Issuer	Approver	Reviewer
Name: Lalit Requester	Name: Sameer Issuer 2	Name: Lalit Approver	Name: Sameer Reviewer
Phone: +91999999990	Phone: +919999999900	Phone: +919988778899	Phone: +911122112211
Requested On: 11-Feb-2025	Issued On: 11-Feb-2025	Approved On: 11-Feb-2025	Reviewed On: 11-Feb-2025
03:30:01 PM	03:32:39 PM	03:35:54 PM	03:37:23 PM

Extension UID: BUVW3J

Extension Conditions	
Is sufficient Illumination to be provided	No
Is security notified of night work	No
Is medical aid resources available	No

Availability & Use of PPE?s	No
Proper Housekeeping to be done on daily basis	No
Any other requirement (If Yes, please specify): Emergency exit are available, Emergency vehicle and First-aid provider shall be assured during the work Main Isolation Switch location is known to All	No
Use of Full body harness with double lanyard & life line or anchor point (while doing hot work at height).	No

Requested	Issued	Approved	Reviewed
Name: Lalit Requester	Name: Sameer Issuer 2	Name: Lalit Approver	Name: Sameer Reviewer
Mobile: +919999999990	Mobile: +91999999900	Mobile: +919988778899	Mobile: +911122112211
Requested On: 11-Feb-2025	Issued On: 11-Feb-2025	Approved On: 11-Feb-2025	Reviewed On: 11-Feb-2025
03:40:51 PM	03:42:01 PM	03:43:19 PM	03:44:40 PM
Duration: 2 hour(s)	Duration: 2 hour(s)	Duration: 2 hour(s)	Duration: 2 hour(s)

Permit To Work History

Created On	Created By	Comment	Attachments
11-Feb-2025 04:01:29 PM	Lalit Approver	The status has changed to Validation_Approved.	
11-Feb-2025 03:58:55 PM	Sameer Issuer 2	The status has changed to Validation_Issued. Assigned Approver: Lalit Approver	
11-Feb-2025 03:57:41 PM	Lalit Requester	Status changed to Validation requested. Following changes are made: PtwUsersInvolved: System.Collections.Generic.List`1[System.Int32] PtwOtherUsersInvolved: Latitude: 17.4452923 Longitude: 78.3779752 Assigned Issuer: Sameer Issuer 2	
11-Feb-2025 03:44:40 PM	Sameer Reviewer	The status has changed to Ext_Reviewed.	
11-Feb-2025 03:43:19 PM	Lalit Approver	The status has changed to Ext_Approved. Assigned Reviewer: Sameer Reviewer	
11-Feb-2025 03:42:01 PM	Sameer Issuer 2	The status has changed to Ext_Issued. Assigned Approver: Lalit Approver	
11-Feb-2025 03:40:51 PM	Lalit Requester	The status has changed to Ext_Requested. Assigned Issuer: Sameer Issuer 2 Duration: 2 hour(s).	
11-Feb-2025 03:37:23 PM	Sameer Reviewer	The status has changed to Reviewed.	
11-Feb-2025 03:35:54 PM	Lalit Approver	The status has changed to Approved. Assigned Reviewer: Sameer Reviewer	
11-Feb-2025 03:32:39 PM	Sameer Issuer 2	The status has changed to Issued. Assigned Approver: Lalit Approver	
11-Feb-2025 03:30:01 PM	Lalit Requester	The status has changed to Requested. Assigned Issuer: Sameer Issuer 2	