




## Ticket Report

Organisation	Telangana R & B
Ticket UID	SC3WN3
Status	Open
Severity	NA
Site	Rangareddy
Reported By	RAJ KUMAR PATIVADA
Mobile Number	+91 9160948627
Others Involved	NA
Category	POTHLES
Describe the ticket	There is a pothole near begumpet
Ticket Image(s)	
Ticket Video(s)	<a href="#">Video 1</a>
Ticket Audio(s)	NA
Ticket File(s)	NA
Created	22-Nov-2024 03:29:46 PM
Modified	22-Nov-2024 03:29:46 PM
Investigation Checklist	NA
Assigned To	NA
Resolved On	NA
Ticket History	NA

To view all Audio(s)/Video(s)/Photo(s)/File(s), Visit:

<https://www.incidentreporter365.com/#/incidents/view/371/17903>

*This is a computer generated report. For queries please mail to [contact@oqsha.com](mailto:contact@oqsha.com)*