



Doc No: MHCPL-EHS-PTW-15

## Permit To Work Report - Concrete Work (Permit UID - APA/APS/ABCCON/CW/0001)

## Permit Information

Permit Information							
Type of permit	Name of project/site	Contractor company	Name of client/contractor				
Concrete Work	Aparna New Site	Abc Constructions	Raj Kumar Pativada				
	Work Inf	formation					
Start date / Close Date	1/12/2025 12:00:00 AM / 1/12/2025 12:00:00 AM	Work location					
Start time / End time	1/17/2025 5:30:00 PM / 1/17/2025 6:00:00 PM	Reference permit no.					
No. of workers	NA	Tools/ equipment to be used					
Scope of work							
Description of work							
		tions ards					
Contact with Eyes	Skin Contact	Inhalation	Electrical Shock				
Hit by Vehicle	Scaffold Collapse 🔽	Slip, Trip & Fall 🔽	Hit by Boom 🗖				
Other Hazards:							
	- Precautio	ons Taken					
Good Access / Egress □	Scaffolding working / Platform 🔽	Adequate illumination 🔽	HIRA Undertaken □				
Good Housekeeping □	Ladder Provided □	Mobile Scaffolding □	Awareness on expected emergencies ? ☐				
Other Precautions::							
	Toolbo	ox Talks					
Topics discussed:		Attach photo: 0					
	Job Spe	cific PPEs					
Safety Helmet □	Safety Shoes <b></b> ✓	Full Body Harness <b></b> ✓	Cover All				
Rubber Hand Gloves	Gum Boots	Goggles	Face Shield				
Other PPEs:							
Safety Considerations							
Required fall protection systems in place.: <b>No</b>	Workers using required fall protection systems.: Yes	Hoisting and rigging operations performed in a safe manner.: <b>No</b>	Guardrails in place and secure.: Yes				
Rebar ends capped to prevent impaling.: <b>No</b>	Wearing safety glasses or goggles when pouring concrete?:	Concrete washout water, collection, containment, disposal.: <b>No</b>	All workers have received basic Hazard Communication training?: No				
MSDSs are available on the site for cement and related products used?: <b>No</b>	ELCB/RCCB provided for Needle Vibrators?: <b>Yes</b>	Proper Edge protection provided in concrete area?: <b>Yes</b>	All vibrators/lights electrical cables laid above 7' (feet) height?: <b>No</b>				
Proper Access/egress provided in concrete pour area?: <b>No</b>	Is Proper Bracing provide for slab supporting props/Posts?:	ls Eye Wash area provided near to concrete poring area?: <b>No</b>	Verification of Pumping equipment's are inspected prior to start?: <b>No</b>				

## Approval and authorization

Requestor	Issuer	Approver	Reviewer
Name: Raj Kumar Pativada Phone: +919160948627 Requested On: 12-Jan-2025 05:30:52 PM	Name: NA Phone: NA Issued On: NA	Name: NA Phone: NA Approved On: NA	Name: NA Phone: NA Reviewed On: NA

## **Permit To Work History**

Created On	Created By	Comment	Attachments
12-Jan-2025 06:01:04 PM	System User	The status has changed to Closed automatically.	
12-Jan-2025 05:30:52 PM	Raj Kumar Pativada	The status has changed to Requested. Assigned Issuer: Sakshi Saxena	