



Doc No: MHCPL-EHS-PTW-15

# Permit To Work Report - Concrete Work (Permit UID - APR/LAL/QWERTY/CW/0007)

## **Permit Information**

Type of permit	Name of project/site	Contractor company	Name of client/contractor
Concrete Work	Lalit's Test Site 001	Aparna Constructions	Lalit Requestor

#### **Work Information**

Start date / Close Date	28-May-2025 / 31-May-2025
Start time / End time	11:28:00 AM / 05:20:00 PM

## Sections

### **Job Details**

Work Location: hyderabad	Number Of Workers: 6	Tools/equipment: wires, mesh	Scope of Work: entire site		
Description Of Work: blast	Reference Permit Number: NA				
Hazards					
Contact with Eyes ☐ Skin Contact ☐ Inhalation ☑ Electrical Shock ☐					
Hit by Vehicle <b></b> ✓	Scaffold Collapse	Slip, Trip & Fall <b></b> ✓	Hit by Boom □		
Other Hazards: NA		•	•		

#### Precautions Taken

Good Access / Egress □	Scaffolding working / Platform	Adequate illumination 🔽	HIRA Undertaken □
Good Housekeeping □	Ladder Provided 🗸	Mobile Scaffolding ☐	Awareness on expected emergencies ? <b>✓</b>
Other Precautions:: NA			

#### **Toolbox Talks**

Attach photo: 0	Topics discussed: NA
-----------------	----------------------

## Job Specific PPEs

Safety Helmet □	Safety Shoes	Full Body Harness 🗸	Cover All
Rubber Hand Gloves □	Gum Boots <b>✓</b>	Goggles	Face Shield <b>▼</b>
Other PPEs: NA			

#### **Safety Considerations**

·				
Required fall protection systems in place.: <b>Yes</b>	Workers using required fall protection systems.: <b>No</b>	Hoisting and rigging operations performed in a safe manner.: <b>NA</b>	Guardrails in place and secure.: <b>No</b>	
Rebar ends capped to prevent impaling.: <b>Yes</b>	Wearing safety glasses or goggles when pouring concrete?: <b>No</b>	Concrete washout water, collection, containment, disposal.: <b>No</b>	All workers have received basic Hazard Communication training?: <b>NA</b>	
MSDSs are available on the site for cement and related products used?: <b>No</b>	ELCB/RCCB provided for Needle Vibrators?: <b>No</b>	Proper Edge protection provided in concrete area?: <b>No</b>	All vibrators/lights electrical cables laid above 7' (feet) height?: <b>No</b>	
Proper Access/egress provided in concrete pour area?: <b>No</b>	Is Proper Bracing provide for slab supporting props/Posts?: No	Is Eye Wash area provided near to concrete poring area?: <b>No</b>	Verification of Pumping equipment's are inspected prior to start?: <b>No</b>	

## Approval and authorization

Requestor_Trial-1	Issuer_Trial-2	Approver_Trial-3	Reviewer_Trial-4
Name: Lalit Requestor Phone: +919989248964 Time: 28-May-2025 11:29:58 AM	Name: NA Phone: NA Time: NA	Name: NA Phone: NA Time: NA	Name: NA Phone: NA Time: NA

## **Permit To Work History**

Created On	Created By	Comment	Attachments
30-May-2025 11:06:46 AM	Lalit Approver	The status has changed to Validation Approved -18.	
30-May-2025 11:05:19 AM	Lalit Issuer	The status has changed to Validation Issued -17. Assigned Approver_Trial-3: Lalit Approver	
30-May-2025 10:52:36 AM	RajKumar Pativada	Section: Job Details Number Of Workers - Tools/equipment - wires, mesh Scope of Work - entire site Description Of Work - blast Reference Permit Number -	
30-May-2025 10:52:35 AM	RajKumar Pativada	Status changed to Validation Requested -14. Following changes are made: Section: Job Details Number Of Workers - Tools/equipment - wires, mesh Scope of Work - entire site Description Of Work - blast Reference Permit Number - Assigned Issuer_Trial-2: Lalit Issuer	
28-May-2025 11:29:58 AM	Lalit Requestor	The status has changed to Requested -3. Assigned Issuer_Trial-2: Lalit Issuer	