Doc No: MHCPL-EHS-PTW-16



Permit To Work Report - De-shuttering Work (Permit UID - APS/HUM/AMBUJ/DW/0005)

Permit Information

Type of permit	Name of project/site	Contractor company	Name of client/contractor
De-shuttering Work	Humpi	AMBUJA CEMENT	Jatin Gupta

Work Information

Start date / Close Date	8/28/2024 12:00:00 AM / 8/28/2024 12:00:00 AM	Work location	
Start time / End time	11/22/2024 3:01:00 PM / 11/23/2024 5:00:00 AM	Reference permit no.	
No. of workers	NA	Tools/ equipment to be used	
Scope of work			
Description of work			

Sections

Hazards

Falling Materials	Fall of Person	Unsafe Working Platform	Improper Handling of Materials
Scaffold Collapse	Slip, Trip & Fall	Poor Housekeeping	Other Hazards:

Precautions Taken

Area Barricading	Safe working platform ☐	Adequate illumination	HIRA Undertaken □
Good Housekeeping	Provide Safety Nets	Proper Supervision	Safe Access / Egress
Awareness on expected emergencies ? □	Other Precautions:		

Toolbox Talks

Topics discussed: Test	Attach photo: 0

Job Specific PPEs

Safety Helmet	Safety Shoes □	Full Body Harness	Cover All
Cotton Hand Gloves	Gum Boots 🗍	Goggles 🗔	Face Shield
Other PPEs:		·	

Safety Considerations

Workers must be provided with safe access to the work.: No	Acrophobia test of worker. (Height Phobia etc.): No	De-shuttering materials should be kept away properly in working areas: No	Do not overload the working platform with materials.: No
Ensure adequate supervision and experienced carpenters for safe works.: No	Ensure proper scaffolding working platform is used.: No		Inspection of working scaffolds, ladders, ramps and crossings.: No
Maintenance of good housekeeping around the working area and Access.: No	Avoid throwing shuttering materials from a height.: No	Using a Pulley & rope system to lower the de-shuttering materials.: No	Guarding of peripheral edges and floor openings.: No
Safety training of workmen involved in formwork?: No	Removal of all unused and hanging forms, loose materials, etc.: No	De-shuttering columns after the development of adequate strength in concrete.: No	Construction loads not placed on the freshly cast slab while removal of formwork.: No

Approval and authorization

Requestor	Issuer	Approver	Reviewer
Name: Jatin Gupta	Name: Jatin Gupta - Iss	Name: Sakshi Saxena	Name: Sonal S
Phone: +919528337699	Phone: +919528337691	Phone: +919821058940	Phone: +919905603211
Requested On: 28-Aug-2024	Issued On: 28-Aug-2024	Approved On: 28-Aug-2024	Reviewed On: 28-Aug-2024
03:01:56 PM	03:03:05 PM	03:03:56 PM	03:04:40 PM

Extension UID: G0E2VE

Extension Conditions		
Is sufficient Illumination to be provided	No	
Is security notified of night work	No	
Is medical aid resources available	No	
Availability & Use of PPE's	No	
Proper Housekeeping to be done on daily basis	No	
Any other requirement (If Yes, please specify): Emergency exit are available, Emergency vehicle and First-aid provider shall be assured during the work Main Isolation Switch location is known to All	No	
Use of Full body harness with double lanyard & life line or anchor point (while doing hot work at height).	No	

Requested	Issued	Approved	Reviewed
Name: Jatin Gupta	Name: Jatin Gupta - Iss	Name: Sakshi Saxena	Name: Sonal S
Mobile: +919528337699	Mobile: +919528337691	Mobile: +919821058940	Mobile: +919905603211
Requested On: 28-Aug-2024	Issued On: 28-Aug-2024	Approved On: 28-Aug-2024	Reviewed On: 28-Aug-2024
03:06:55 PM	03:08:16 PM	03:10:08 PM	03:10:42 PM
Duration: 5 hour(s)	Duration: 5 hour(s)	Duration: 7 hour(s)	Duration: 7 hour(s)

Extension UID: CAWY4L

Extension Conditions	
Is sufficient Illumination to be provided	No
Is security notified of night work	No
Is medical aid resources available	No
Availability & Use of PPE's	No
Proper Housekeeping to be done on daily basis	No
Any other requirement (If Yes, please specify): Emergency exit are available, Emergency vehicle and First-aid provider shall be assured during the work Main Isolation Switch location is known to All	No
Use of Full body harness with double lanyard & life line or anchor point (while doing hot work at height).	No

Requested	Issued	Approved	Reviewed
Name: Jatin Gupta	Name: Jatin Gupta - Iss	Name: Sakshi Saxena	Name: Sonal S
Mobile: +919528337699	Mobile: +919528337691	Mobile: +919821058940	Mobile: +919905603211
Requested On: 28-Aug-2024	Issued On: 28-Aug-2024	Approved On: 28-Aug-2024	Reviewed On: 28-Aug-2024
08:52:38 PM	08:53:16 PM	09:12:37 PM	09:13:03 PM
Duration: 4 hour(s)	Duration: 4 hour(s)	Duration: 4 hour(s)	Duration: 4 hour(s)

Permit To Work History

Created On	Created By	Comment	Attachments
29-Aug-2024 05:04:46 AM	Raj Kumar Pativada	Cancelled. The status has changed to Cancelled.	
28-Aug-2024 09:13:03 PM	Sonal S	The status has changed to Ext_Reviewed.	
28-Aug-2024 09:12:37 PM	Sakshi Saxena	The status has changed to Ext_Approved. Assigned Reviewer: Sonal Sharma	
28-Aug-2024 08:53:16 PM	Jatin Gupta - Iss	The status has changed to Ext_Issued. Assigned Approver: Abhinav Srivastava	
28-Aug-2024 08:52:38 PM	Jatin Gupta	The status has changed to Ext_Requested. Assigned Issuer: Jatin Gupta - Iss Duration: 4 hour(s).	
28-Aug-2024 03:10:42 PM	Sonal S	The status has changed to Ext_Reviewed.	
28-Aug-2024 03:10:08 PM	Sakshi Saxena	The status has changed to Ext_Approved. Assigned Reviewer: Sonal Sharma Duration: 7 hour(s).	
28-Aug-2024 03:08:16 PM	Jatin Gupta - Iss	The status has changed to Ext_Issued. Assigned Approver: Abhinav Srivastava	
28-Aug-2024 03:06:55 PM	Jatin Gupta	The status has changed to Ext_Requested. Assigned Issuer: Jatin Gupta - Iss Duration: 5 hour(s).	

28-Aug-2024 03:04:40 PM	Sonal S	The status has changed to Reviewed.	
28-Aug-2024 03:03:56 PM	Sakshi Saxena	The status has changed to Approved. Assigned Reviewer: Sonal Sharma	
28-Aug-2024 03:03:05 PM	Jatin Gupta - Iss	The status has changed to Issued. Assigned Approver: Abhinav Srivastava	
28-Aug-2024 03:01:56 PM	Jatin Gupta	The status has changed to Requested. Assigned Issuer: Jatin Gupta - Iss	