



Doc No: MHCPL-EHS-PTW-07

Permit To Work Report - Hot Work (Permit UID - APS/NIS/OQSHAI/HW/0001)

Permit Information

Type of permit	Name of project/site	Contractor company	Name of client/contractor
Hot Work	Nishada	OQSHA India	Sayan Mondal

Work Information

Start date / Close Date	1/18/2025 12:00:00 AM / 1/19/2025 12:00:00 AM	Work location	Durgapur
Start time / End time	1/18/2025 6:30:00 AM / 1/18/2025 6:00:00 PM	Reference permit no.	HW-001
No. of workers	1000	Tools/ equipment to be used	Hammer
Scope of work	Permit To Work		
Description of work	Hot Work		

Sections

Hazards

Electrical Shock 🗸	Carbon Fumes 🔽	Arc Flash ✓	Burns 🗸
Fire /Explosion ✓	Person Fall 🗸	Equipment Fall 🗸	Other Hazards:

Attachments



Precautions Taken


Isolation 🗸	LOTO Applied	Isolation Switch Available	Cordoned Area
HIRA Undertaken ✓	Signage's Provided	SOP 🔽	Grounding Provided 🔽
ELCB / RCCB Provided	Awareness on expected emergencies ? ✓	Other Precautions:: Other Precaution	

Attachments



Toolbox Talks

Topics discussed: Toolbox Talks Pvt Ltd	Attach photo: 1



Job Specific PPEs

Safety Helmet ✓	Safety Shoes 🔽	Full Body Harness □	Cover All 🔽
Welding Face Shield ☑	Leather Hand Gloves ☐	Leather Apron ☐	UV Protection Shield ☐
Other PPE's:			

Attachments



Has the area at the work location been cleared of all the combustible materials & any other lubricants etc?: Yes	Has a flashback arrestor at both sides (cylinder & torch) been provided to the gas-cutting set?: Yes	Have Suitable Fire Extinguishers/sand buckets been kept handy at the work site?: Yes	Have Welding Screen (Yellow) / wet gunny bag/fire blanket been used to protect against sparks?: NA
Vertical clearance. (at least 2 meters above the platform) (Supervision should be provided if sufficient clearance is not available): No	Is barricading being provided below while doing work at height?: NA	Is the gas-cutting cylinder checked for any leakages?: NA	Are the gas cylinders secured in a trolley using chains?: Yes
Do all workers involved in hot work have proper training on safety procedures and equipment use?: Yes	Do welding machines have ELCB/RCCB and proper earthing?: Yes	Availability and use of PPEs. (Mandatory PPE + Leather Apron, Welding Face Shield, Leather Hand Gloves): NA	Use of Full body harness with double lanyard & lifeline or anchor point.(while doing hot work at height): Yes
Any other requirement (If Vec			

Any other requirement (If Yes, please specify): Emergency exits are available, and Emergency vehicle and First-aid providers shall be assured during the work The Main Isolation Switch location is known to All Shock Treatment chart is available and is understood through TBT.: Yes

Attachments





Approval and authorization

Requestor	Issuer	Approver	Reviewer
Name: Sayan Mondal Phone: +917735901811 Requested On: 18-Jan-2025 01:28:58 AM	Name: Sayan Mondal Issuer Phone: +918967697371 Issued On: 18-Jan-2025 01:38:11 AM	Name: Sayan Mondal Approver Phone: +917586016748 Approved On: 18-Jan-2025 01:39:11 AM	Name: Raj Kumar Pativada Phone: +919160948627 Reviewed On: 18-Jan-2025 01:39:48 AM

Extension UID: NO95MG

Extension Conditions Requested Issued **Approved** Reviewed Name: Sayan Mondal Name: Sayan Mondal Issuer Name: Sayan Mondal Name: Raj Kumar Pativada Mobile: +918967697371 Issued On: 18-Jan-2025 Mobile: +917735901811 Mobile: +919160948627 Approver Mobile: +917586016748 Requested On: 18-Jan-2025 Reviewed On: 18-Jan-2025 01:55:14 AM 01:56:48 AM Approved On: 18-Jan-2025 02:05:33 AM 01:58:36 AM Duration: 3 hour(s) Duration: 3 hour(s) **Duration**: 3 hour(s) **Duration**: 3 hour(s)

Permit To Work History

Created On	Created By	Comment	Attachments
18-Jan-2025 09:01:05 PM	System User	The status has changed to Temporarily_Suspended automatically.	
18-Jan-2025 02:05:33 AM	Raj Kumar Pativada	The status has changed to Ext_Reviewed.	

r	_		T
18-Jan-2025 01:58:37 AM	Sayan Mondal Approver	The status has changed to Ext_Approved. Assigned Reviewer: Raj Kumar Pativada	
18-Jan-2025 01:56:48 AM	Sayan Mondal Issuer	The status has changed to Ext_Issued. Assigned Approver: Sayan Mondal Approver	
18-Jan-2025 01:55:14 AM	Sayan Mondal	The status has changed to Ext_Requested. Assigned Issuer: Sayan Mondal Issuer Duration: 3 hour(s).	
18-Jan-2025 01:39:48 AM	Raj Kumar Pativada	The status has changed to Reviewed.	
18-Jan-2025 01:39:48 AM	Raj Kumar Pativada	Users involved updated to: Sayan Mondal, Sayan Mondal Issuer Other users involved updated to: Karan, Arjun	
18-Jan-2025 01:39:11 AM	Sayan Mondal Approver	The status has changed to Approved. Assigned Reviewer: Raj Kumar Pativada	
18-Jan-2025 01:39:10 AM	Sayan Mondal Approver	Following changes are made in the PTW data: Section: Safety Considerations Are the gas cylinders secured in a trolley using chains? - Yes Users involved updated to: Sayan Mondal,Sayan Mondal Issuer Other users involved updated to: Karan, Arjun	
18-Jan-2025 01:38:11 AM	Sayan Mondal Issuer	The status has changed to Issued. Assigned Approver: Sayan Mondal Approver	
18-Jan-2025 01:38:11 AM	Sayan Mondal Issuer	Following changes are made in the PTW data: NoOfWorkers: 1000 Section: Toolbox Talks Topics discussed - Toolbox Talks Pvt Ltd Section: Safety Considerations Use of Full body harness with double lanyard & lifeline or anchor point.(while doing hot work at height) - Yes Any other requirement (If Yes, please specify): Emergency exits are available, and Emergency vehicle and First-aid providers shall be assured during the work The Main Isolation Switch location is known to All Shock Treatment chart is available and is understood through TBT Yes Users involved updated to: Sayan Mondal,Sayan Mondal Issuer Other users involved updated to: Karan, Arjun	
18-Jan-2025 01:28:58 AM	Sayan Mondal	The status has changed to Requested. Assigned Issuer: Sayan Mondal Issuer	
	•		•