Other PPE's:

Doc No: FCP-EHS-PTW-01



# Permit To Work Report - General Work (Permit UID - FBD/FCP/SRISAI/GW/0002)

# **Permit Information**

Type of permit	Name of project/site	Contractor company	Name of client/contractor
General Work	Food Creations Private Limited	Sri Sainath Plastic Industry	Lalit -Requestor

#### **Work Information**

Start date / Close Date	25-Mar-2025 / 25-Mar-2025	Work location	NA
Start time / End time	12:44:00 AM / 05:29:00 AM	Reference permit no.	NA
No. of workers	NA	Tools/ equipment to be used	NA
Scope of work	NA		
Description of work	NA		

### Sections

Sections					
Work Location:	Number Of Workers:	Tools/equipment:	Scope of Work:		
Description Of Work:	Reference Permit Number:				
	Hazards				
Falling Materials	Fall of Person ☐	Unsafe Working Platform	Improper Handling of Materials		
Scaffold Collapse	Slip, Trip & Fall ☐	Poor Housekeeping	Other Hazards:		
	Precautions Taken				
Area Barricading	Safe working platform ☐	Adequate illumination	HIRA Undertaken □		
Good Housekeeping ☐	Provide Safety Nets ☐	Proper Supervision   ☐	Safe Access / Egress □		
Awareness on expected emergencies ? ☐	Other Precautions:		_		
Job Specific PPEs					
Safety Helmet □	Safety Shoes	Full Body Harness	Cover All		
Cotton Hand Gloves	Gum Boots □	Goggles □	Face Shield		

### **Toolbox Talks**

Topics discussed:	Attach photo: 0	Signature: Signed by Prashanth Issuer at 25-Mar-2025 07:15 PM.
-------------------	-----------------	--

# **Safety Considerations**

Workers must be provided with safe access to the work.: <b>No</b>	Acrophobia test of worker. (Height Phobia etc.): <b>No</b>	De-shuttering materials should be kept away properly in working areas: <b>No</b>	Do not overload the working platform with materials.: <b>No</b>
Ensure adequate supervision and experienced carpenters for safe works.: <b>No</b>	Ensure proper scaffolding working platform is used.: <b>No</b>	The de-Shuttering area should be barricaded before starting work.: <b>No</b>	Inspection of working scaffolds, ladders, ramps and crossings.: <b>No</b>
Maintenance of good housekeeping around the working area and Access.: <b>No</b>	Avoid throwing shuttering materials from a height.: <b>No</b>	Using a Pulley & rope system to lower the de-shuttering materials.: <b>No</b>	Guarding of peripheral edges and floor openings.: <b>No</b>
Safety training of workmen involved in formwork?: <b>No</b>	Removal of all unused and hanging forms, loose materials, etc.: <b>No</b>	De-shuttering columns after the development of adequate strength in concrete.: <b>No</b>	Construction loads not placed on the freshly cast slab while removal of formwork.: <b>No</b>

# Approval and authorization

Requestor	Area In Charge	Quality In Charge	Safety In charge
Name: Lalit -Requestor	Name: Prashanth Issuer	Name: Sayan Mondal REQ	Name: Prashanth Reviewer
Phone: +919959993362	Phone: +917993748762	Phone: +918967697371	Phone: +919573313524
Time: 25-Mar-2025 07:14:53	Time: 25-Mar-2025 07:16:27	Time: 27-Mar-2025 07:52:23	Time: 27-Mar-2025 07:53:29
PM	PM	PM	PM

# **Permit To Work History**

Created On	Created By	Comment	Attachments
27-Mar-2025 07:53:29 PM	Prashanth Reviewer	The status has changed to Approved.	
27-Mar-2025 07:52:23 PM	Sayan Mondal REQ	The status has changed to Quality Verfied. Assigned Safety In charge: Prashanth Reviewer	
25-Mar-2025 07:16:27 PM	Prashanth Issuer	The status has changed to Accepted. Assigned Quality In Charge: Sayan Mondal REQ	
25-Mar-2025 07:15:45 PM	Prashanth Issuer	Section: Toolbox Talks Signed by Prashanth Issuer at 25-Mar-2025 07:15 PM.	
25-Mar-2025 07:14:53 PM	Lalit -Requestor	The status has changed to Requested. Assigned Area In Charge: Prashanth Issuer	